



186 Family Evaluation Board

Specification Update

December 1997

Notice: The name of product may contain design defects or errors known as errata. Characterized errata that may cause the name of product's behavior to deviate from published specifications are documented in this specification update.

Order Number: 272893-002



Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

MPEG is an international standard for video compression/decompression promoted by ISO. Implementations of MPEG CODECs, or MPEG enabled platforms may require licenses from various entities, including Intel Corporation.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature may be obtained by calling 1-800-548-4725 or by visiting Intel's website at <http://www.intel.com>.

Copyright © Intel Corporation, 1997

*Third-party brands and names are the property of their respective owners.



Contents

Revision History	5
Preface.....	6
Summary Table of Changes	7
Identification Information.....	9
Errata	10
Specification Changes	11
Specification Clarifications	12
Documentation Changes	13



Revision History

Date	Version	Description
12/17/97	002	Added documentation change 4. Reformatted spec update to new page size.
07/01/96	001	This is the new Specification Update document. It contains all identified errata published prior to this date.

Preface

As of July, 1996, Intel's Computing Enhancement Group has consolidated available historical device and documentation errata into this new document type called the Specification Update. We have endeavored to include all documented errata in the consolidation process, however, we make no representations or warranties concerning the completeness of the Specification Update.

This document is an update to the specifications contained in the Affected Documents/Related Documents table below. This document is a compilation of device and documentation errata, specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in Nomenclature are consolidated into the specification update and are no longer published in other documents.

This document may also contain information that was not previously published.

Affected Documents/Related Documents

Title	Order
<i>EV80C186EA/XL Evaluation Board User's Manual</i>	272124-001
<i>EV80C186EB Evaluation Board User's Manual</i>	272068-002
<i>EV80C186EC Evaluation Board User's Manual</i>	272125-001
<i>Intel 186 EB/EC Evaluation Board User's Manual</i>	272986-001

Nomenclature

Errata are design defects or errors. These may cause the published (component, board, system) behavior to deviate from published specifications. Hardware and software designed to be used with any component, board, and system must consider all errata documented.

Specification Changes are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

Documentation Changes include typos, errors, or omissions from the current published specifications. These will be incorporated in any new release of the specification.

Note: Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, etc.).

Summary Table of Changes

The following table indicates the errata, specification changes, specification clarifications, or documentation changes which apply to the Intel 186 Family product. Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

Codes Used in Summary Table

Stepping

X:	Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.
(No mark)	
or (Blank box):	This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

Page

(Page):	Page location of item in this document.
---------	---

Status

Doc:	Document change or update will be implemented.
Fix:	This erratum is intended to be fixed in a future step of the component.
Fixed:	This erratum has been previously fixed.
NoFix:	There are no plans to fix this erratum.
Eval:	Plans to fix this erratum are under evaluation.

Row



Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.

Errata

No.	Steppings			Page	Status	ERRATA
	EA/XL	EB	EC			
1			X	10	NoFix	System Expansion Considerations
2			X	10	NoFix	Flash VPP Switch

Specification Changes

No.	Steppings			Page	Status	SPECIFICATION CHANGES
	EA/XL	EB	EC			
1		X		11	Doc	Serial Connector (P2)
2		X		11	Doc	Expansion Buffer Control (U25 And U27)

Specification Clarifications

No.	Steppings			Page	Status	SPECIFICATION CLARIFICATIONS
	EA/XL	EB	EC			
						None for this revision of this specification update.

Documentation Changes

No.	Document Revision	Page	Status	DOCUMENTATION CHANGES
1	272124-001	13		EA_EXP PLD (U26)
2	272125-001	13		Refresh Problem
3	272125-001	14		Unconnected Header Pins
4	272986-001	14		Table A-2, Sheet 2 of 3 on Page A-5

Identification Information

Markings

Intel 186 Family processors may be identified electrically according to device type and stepping. Refer to the datasheet for instructions on how to obtain the identifier number.

Product # EV80C186EA/XL

EV80C186EB

EV80C186EC

Errata

1. System Expansion Considerations

Problem: The present configuration assumes GCS1# is used for all Expansion Bus accesses.

Implication: If you plan to use the GCS2# through GCS7# (chip-select function) for system expansion, this is not possible in the present system configuration. These pins can be used as port pins.

Workaround: However, by modifying the EC_PLD2 equations, the other General Chip Select lines could be used to access expansion memory. The equations controlling the expansion bus buffers would have to be modified to allow reading and writing of data. Specifically, the “NUMERICS” reference should be removed from the nHI_XCR_EN, nX_XC_EN and the nLO_XCR_EN signal equations.

Note: The revised JEDEC file for EC_PLD2 can be found on the Applications BBS under filename EVEC_FIX.ZIP.

Status: There are no plans to correct this behavior. Refer to Summary Table of Changes to determine the affected stepping(s).

2. Flash V_{pp} Switch

Problem: Page 1-12 of the *EV80C186EC Evaluation Board User's Manual* (Order Number 272125-001) makes a reference to FLASH V_{pp} Switch. This operation is not functional.

Page F-4 of the User's Manual, the circuit schematics show the presence of an inverter IC, U7. This IC does not exist on the board (which makes the FLASH V_{pp} Switch operation invalid).

Do Not switch the E1 jumper to position BC while the EPROMs are on the board. This will damage the EPROMs.

Implication: FLASH V_{pp} Switch is not functional.

Workaround: N/A

Status: Refer to Summary Table of Changes to determine the affected stepping(s).

Specification Changes

1. Serial Connector (P2)

Issue: The evaluation board schematics on page A-7 of the *EV80C186EB Evaluation Board User's Manual* (Order Number 272068-002) is incorrect. Connector P2 is labeled as a DB9 Female connector. On the actual board, this connector is a DB9 Male.

As a result, all signals are reversed. TXD0 (P2-3) is unaffected (it is centered on the connector).

RXD0 needs to be connected to P2-4 and CTS0 needs to be connected to P2-7. Also, ground must be connected to pin P2-1. A simple way to fix this problem is to flip-over the ribbon cable attached to the female part of the connector.

Affected Docs: *EV80C186EB Evaluation Board User's Manual*, order number 272068-002.

2. Expansion Buffer Control (U25 And U27)

Issue: This problem initiates in the PLD at U16. U16-16 is not the PASSIVE output connected to the LED array. U16-16 is an output, an inverted DT/R signal. U16-13 is not grounded, it is connected to the 80C18xEB DT/R output (U8-16).

On the schematics, the DIR pins of the 74AC245 buffers are connected to the DT/R output of the processor. This is not the case. U25-1 and U27-1 (DIR) pins are connected to U16-16, the inverted DT/R signal.

This configuration will not work (buffers will drive data in the wrong direction).

To correct the problem, cut the trace from U16-16 to U25-1 and U27-1. Connect a wire from U16-13 to U25-1 and U27-1. This connects the processor DT/R signal to the buffer direction control.

Affected Docs: *EV80C186EC Evaluation Board User's Manual*, order number 272125-001.

Specification Clarifications

None for this revision of this specification update.

Documentation Changes

1. EA_EXP PLD (U26)

Issue:

1. PLD Equation prohibits reads from the expansion bus in the EV80C186EA/XL Evaluation Board. The existing equation:

```
DRT = !DTR # DTR & EXPDEN
```

always evaluates to 1 when EXPDEN = 1 (expansion bus cycle in progress). This causes the output of the PLD to go low. The 74AC245 buffers will always write data to the expansion bus but not read data from the expansion bus. To function correctly, the equation needs to be changed to:

```
DRT = !DTR & EXPDEN
```

2. An incorrect PLD equation, in appendix D of the *EV80C186EC Evaluation Board User's Manual*, causes only certain blocks of memory space in DRAM to be refreshed in addition to mirroring for certain segments. The bug is in the following PLD equation (EC_PLD1):

```
old equation:  M8 = (!nMUX&LA9)#(nMUX&LA18);
M8.OE = 'B' 1;  /** TURN ON THE OUTPUT **/
```

It should be revised as the following:

```
new equation:  M8 = (nMUX&LA9)#(!nMUX&LA18);
M8.OE = 'B' 1;  /** TURN ON THE OUTPUT **/
```

Note: The JEDEC file for EC_PLD1 can be found on Intel's WWW site. Search for EVEC_FIX.ZIP.

Affected Docs: *EV80C186EA/XL Evaluation Board User's Manual*, order number 272124-001; *EV80C186EC Evaluation Board User's Manual*, order number 272125-001.

2. Refresh Problem

Issue:

This does not affect boards using the Paradigm Software. In the RISM monitor, the DRAM Refresh Base Address register is programmed incorrectly. The DRAM Base address is set to 0000H, and the DRAM chip select is never activated, so the DRAM is never refreshed. This is not a problem if user code is loaded into SRAM and does not use DRAM. There are two possible fixes:

1. Revise the RISM source code and burn two new EPROMs. Make sure the EPROMs will work with the processor type being used (186 or 188). All bytes need to be programmed in the low-byte and every other odd byte must be burned into the high-byte. It may help to view to current EPROM contents on the programmer to understand how the data is stored.
2. The RFBASE register can be reprogrammed in the user's code to refresh the correct memory range. The following code sequence will do this:

```
MOV DX, 0FF80H;GCS0ST REGISTER (DRAM Chip Select)
IN AX, DX; READ GCS0ST CONTENTS
AND AX, 0FFF0H; MASK WAIT-STATE BITS
SAR AX, 9 ; SHIFT AX RIGHT 9 BITS
MOV DX, 0FFB0H; RFBASE REGISTER
OUT DX, AL; REPROGRAM REFRESH BASE ADDRESS
```

The user can optionally disable DRAM refresh before executing this code, but it should make no difference if the refresh counter is set to zero when the base address is programmed.

Note: The HEX file for RISM code can be found on Intel's WWW site. Search for EVEC_FIX.ZIP.

Affected Docs: *EV80C186EC Evaluation Board User's Manual*, order number 272125-001.

3. Unconnected Header Pins

Issue: Page 1-13 of the *EV80C186EC Evaluation Board User's Manual (272125-001)* makes a reference to an errata on the boards marked with revision number 2.0. This errata is found on boards marked with the Rev. 1.1 label. Rev. 1.1 is the latest revision of this evaluation board, there is no Rev. 2.0 board. In addition to this errata, there are several other unconnected header pins. The following table gives a listing of the unconnected pins and their intended routes.

Header/Jumper Name	Header Pin Number/Jumper Post	Processor Pin Name	Processor Pin Number
E2 Jumper	B Post	P2.4/RXD1	20
E3 Jumper	B Post	P2.7/CTS1#	23
JP4	43	S2	80
JP5	7	P3.2/DMAI0	26
JP5	3	P3.0/RX11	24

Affected Docs: *EV80C186EC Evaluation Board User's Manual*, order number 272125-001.

4. Table A-2, Sheet 2 of 3 on Page A-5

Issue: Delete the following row:

XU9	Meritec # 980021-44-01	SMT 44 pin socket	SOP44	SMT 44 pin socket,w/o alignment pins
-----	---------------------------	-------------------	-------	--

(This part was used in the prototype, but is not used in production boards.)

In the following row, delete the word "Socketed" from the Notes column.

U9	INTEL #PA28F400BV -T60	4Mb,boot blk,flash		Socketed
----	---------------------------	--------------------	--	----------

Affected Docs: *Intel 186 EB/EC Evaluation Board User's Manual*, order number 272986-001.