



# **80C186EA/80C188EA AND 80L186EA/80L188EA EMBEDDED MICROPROCESSORS SPECIFICATION UPDATE**

Release Date: August, 1997

Order Number: 272896-003

The 80C186EA/80C188EA and 80L186EA/80L188EA microprocessors may contain design defects or errors known as errata which may cause the products to deviate from published specifications. Current characterized errata are documented in this specification update.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to specifications and product descriptions at any time, without notice.

Contact your local Intel sales office or your distributor to obtain the latest specifications before placing your product order.

\*Third-party brands and names are the property of their respective owners.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature, may be obtained from:

Intel Corporation  
P.O. Box 7641  
Mt. Prospect IL 60056-7641

or call in North America 1-800-879-4683, Europe 44-0-1793-431-155,  
France 44-0-1793-421-777, Germany 44-0-1793-421-333, other countries 708-296-9333

Copyright © 1997, INTEL CORPORATION

## CONTENTS

REVISION HISTORY .....	1
PREFACE .....	2
SUMMARY TABLE OF CHANGES .....	4
IDENTIFICATION INFORMATION .....	7
ERRATA .....	9
SPECIFICATION CHANGES .....	20
SPECIFICATION CLARIFICATIONS .....	21
DOCUMENTATION CHANGES .....	22



**REVISION HISTORY**

<b>Rev. Date</b>	<b>Version</b>	<b>Description</b>
08/18/97	003	Changed Affected Steppings in the Errata table. Errata 3, 4 and 5 do not affect the B stepping.
06/24/97	002	Changed AX register contents in Stack Operation figure (Documentation Change #4)
07/01/96	001	This is the new Specification Update document. It contains all identified errata published prior to this date.

## PREFACE

As of July, 1996, Intel has consolidated available historical device and documentation errata into this document type called the Specification Update. We have endeavored to include all documented errata in the consolidation process, however, we make no representations or warranties concerning the completeness of the Specification Update.

This document is an update to the specifications contained in the Affected Documents/Related Documents table below. This document is a compilation of device and documentation errata, specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in Nomenclature are consolidated into the specification update and are no longer published in other documents.

This document may also contain information that was not previously published.

### ***Affected Documents/Related Documents***

Title	Order
<i>80C186EA/80C188EA Microprocessor User's Manual</i>	270950-003
<i>80C186EA/80C188EA and 80L186EA/80L188EA 16-Bit High-Integration Embedded Processors datasheet</i>	272432-003

### ***Nomenclature***

**Errata** are design defects or errors. These may cause the published (component, board, system) behavior to deviate from published specifications. Hardware and software designed to be used with any component, board, and system must consider all errata documented.

**Specification Changes** are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

**Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

**Documentation Changes** include typos, errors, or omissions from the current published specifications. These will be incorporated in any new release of the specification.

**NOTE:**

Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, etc.).

## SUMMARY TABLE OF CHANGES

The following table indicates the errata, specification changes, specification clarifications, or documentation changes which apply to the 80x186EA/80x188EA product. Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

### *Codes Used in Summary Table*

#### **Stepping**

X:	Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.
(No mark) or (Blank box):	This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

#### **Page**

(Page):	Page location of item in this document.
---------	---

#### **Status**

Doc:	Document change or update will be implemented.
Fix:	This erratum is intended to be fixed in a future step of the component.
Fixed:	This erratum has been previously fixed.
NoFix:	There are no plans to fix this erratum.
Eval:	Plans to fix this erratum are under evaluation.

#### **Row**

<b> </b>	Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.
----------	---

**Errata**

No.	Steppings			Page	Status	ERRATA
	A <sup>2</sup>	B <sup>2</sup>	L <sup>1</sup> , B			
1	X	X	X	9	Fixed	INTx/INTAx
2	X	X		16	NoFix	NMINmi Entering Powerdown Mode on the 80C186/80C188 A/EB/ECx
3	X			18	Fixed	RESIN# Hysteresis
4	X			19	Fixed	TEST/BUSY#, RD#/QSMD#, LCS#, and UCS# V <sub>il</sub> Problem
5	X			19	Fixed	Excessive Leakage in ONCE Mode

## NOTES:

1. L stands for 80L186EA/80L188EA.
2. Errata only affects the steppings that are listed above. Refer to the table in the Identification Information section in this Update for clarification.

### ***Specification Changes***

No.	Steppings			Page	Status	SPECIFICATION CHANGES
						None for this revision of this specification update.

### ***Specification Clarifications***

No.	Steppings			Page	Status	SPECIFICATION CLARIFICATIONS
						None for this revision of this specification update.

### ***Documentation Changes***

No.	Document Revision	Page	Status	DOCUMENTATION CHANGES
1	270950-003	22	Doc	82C59A Interface Pin Incorrectly Listed
2	270950-003	22	Doc	Reset State for Interrupt Mask Register Incorrectly Listed
3	270950-003	22	Doc	Incorrect Flow Chart Labels
4	270950-003	22	Doc	Incorrect AX Register Contents

## IDENTIFICATION INFORMATION

### *Markings*

80x186EA/80x188EA processors may be identified electrically according to device type and stepping. Refer to the data sheet for instructions on how to obtain the identifier number.

A-step sample devices may be identified as follows:

The product is marked with a 5-character QDF number just below the product identifier.

The table below lists which QDF numbers apply to A-step devices.

<b>Product</b>	<b>QDF Number (all packages/speeds)</b>
80C186EA	Q8423, Q8553, Q8426, Q8428, Q8430
80C188EA	Q8408, Q8427, Q8424

A-step production devices may be identified as follows:

The product is marked with a 9-character alphanumeric Intel FPO number underneath the product code number.

For A-step EA devices, the ninth character is "A".

Regardless of sample or production status, there is a STEPID register which may be examined through software. For A-step EA devices, the register contains a value of 01H.

**Table 1. Parts Affected by the INTx/INTAx Errata**

<b>Device</b>	<b>Stepping</b>	<b>9th Character</b>
80C186XL/80C188XL	B	A
80C186EA/80C188EA	A	A
80C186EA/80C188EA	B	B
80L186EA/80L188EA	B	B
80C186EB/80C188EB	A	A*
80C186EB/80C188EB	B0	B
80C186EB/80C188EB	B1	C
80L186EB/80L188EB	A	A*
80L186EB/80L188EB	B0	B
80L186EB/80L188EB	B1	C

## ERRATA

### 1. *INTx/INTAx*

**PROBLEM:** An internal problem with the Interrupt Control Unit in cascade mode can cause no acknowledge cycle on the INTA1# line after an interrupt on INT1 or on INTA0# after an interrupt on INT0.

There are two cases. Problem 1: Interrupt 1 is configured in cascaded mode and a higher priority interrupt exists. Problem 2: Interrupt 0 is configured in cascaded mode and interrupt 1 is higher priority.

#### **Problem 1:**

An interrupt acknowledge for INT1 is not generated on INTA1#. If two interrupts are in cascade mode, the interrupt acknowledge is generated on INTA0#.

#### **Condition:**

Another interrupt of higher priority occurs after the decision is made to service Interrupt 1 but before the expected acknowledge cycle on INTA1#.

#### **Configuration:**

1. Master Mode
2. INT1 is in Cascade mode and enabled.
3. An Interrupt of higher priority than INT1 is enabled (DMA, Timers, INT lines, Serial, etc.).

#### **Problem 2:**

An interrupt acknowledge for INT0 is not generated on INTA0#. If two interrupts are in cascade mode, the interrupt acknowledge is generated on INTA1#.

#### **Condition:**

Interrupt 1, configured as higher priority than interrupt 0, occurs after the decision is made to service Interrupt 0 but before the expected acknowledge cycle on INTA0#.


#### **Configuration:**

1. Master Mode
2. INT0 is in Cascade mode and enabled.
3. INT1 is enabled and higher priority than INT0.

### Problem 1 Description

Note: In the cases below, the interrupt controller has already decided to service the INT1 interrupt before the higher priority interrupt occurs.


Correct operation of the device acknowledges the interrupt on INTA1# after an interrupt on INT1. Normally, this occurs even if there is a higher priority interrupt after INT1 but before the acknowledge (Figure 1).



**Figure 1. Correct INT1 Acknowledge Sequence with Higher Priority Timer Interrupt**

\*Note: This interrupt could be any of the following: DMA, Timers, Serial, INT0, or INT2.


The errata occurs when a higher priority interrupt occurs between INT1 and its expected acknowledge. The processor completes internal interrupt acknowledge cycles as seen on the status lines but no acknowledge cycle is sent on the INTA1# output (Figure 2).



**Figure 2. Incorrect INT1 Acknowledge Sequence with Higher Priority Timer Interrupt**

\*Note: This interrupt could be any of the following: DMA, Timers, Serial, INT0, or INT2.

If INT0 and INT1 are configured in cascade mode and a higher priority interrupt occurs between INT1 and its expected acknowledge, then the acknowledge will appear on INTA0# instead (Figure 3).




**Figure 3. INT0 And INT1 Acknowledge Failure due to Higher Priority Timer Interrupt**

\*Note: This interrupt could be any of the following: DMA, Timers, Serial, or INT0.

**Problem 2 Description**

Note: In the cases below, the interrupt controller has already decided to service the INT0 interrupt before the higher priority INT1 occurs.


Correct operation acknowledges INT0 on INTA0#. Normally, this occurs even if there is a higher priority INT1 after INT0 but before the acknowledge (Figure 4).



**Figure 4. Correct INT0 Acknowledge Operation with a Simultaneous INT1**

\*Note: INT1 is the only interrupt that causes the errata to occur.


The errata occurs when INT1, which is higher priority than INT0, occurs between INT0 and its expected acknowledge. The processor completes internal interrupt acknowledge cycles as seen on the status lines but no acknowledge cycle is sent on the INTA0# output (Figure 5).



**Figure 5. Incorrect INT0 Acknowledge Operation with a Simultaneous INT1**

\*Note: This problem occurs only if INT1 is higher priority than INT0.

If INT0 and INT1 are configured in cascade mode and the higher priority INT1 occurs between INT0 and its expected acknowledge, then the acknowledge will appear on INTA1# instead of INTA0# (Figure 6).



**Figure 6. INT0 and INT1 Acknowledge Failure Due to the Higher Priority INT1**

\*Note: This problem occurs only if INT1 is higher priority than INT0.

**IMPLICATION:** If two cascaded interrupt controllers are used, the interrupt acknowledge can be sent to the wrong controller. This can cause no acknowledge cycle on the INTA1# line after an interrupt on INT1 or on INTA0# after an interrupt on INT0.

In a system with a single external interrupt controller, the errata will cause no acknowledge to be sent on the INTA# output. Internally, the device still functions normally, only the state of the output pin is incorrect. The Interrupt Request Register and Interrupt Service Register will operate normally.

The 186 will still run two back-to back interrupt acknowledge cycles. If the external interrupt controller does not receive the two interrupt acknowledge pulses, it will never drive the interrupt type onto the data bus. Therefore, the 186 will read an invalid interrupt type.

### Software Workaround:

#### CONDITION

#### WORKAROUND

- |   |   |
|---|---|
| 1. Only INT1 is configured in cascade mode and is lower priority than at least one other interrupt. | Use only INT0 in cascade mode instead, or make INT1 the highest priority interrupt, or use hardware workaround. |
| 2. INT1 and INT0 are both in cascade mode.  | Use only one interrupt in cascade mode, or use hardware workaround.   |
| 3. Only INT0 is configured in cascade mode and is lower priority than INT1.                         | Make INT0 higher priority than INT1, or use hardware workaround.  |

Table 2. Software Workarounds for Problem 1

Master Mode	Cascade Mode	INT1 Priority vs. any other interrupt	INTA1 Problem	INTA0 Problem	Workaround
Yes	INT0 and INT1	N/A	Yes	Yes	Use only one interrupt line in cascade mode or H/W workaround
Yes	INT1 only	Lower	Yes	No	Change to INT0 or make INT1 highest priority
Yes	INT1 only	Higher	No	No	N/A
Yes	INT0 only	N/A	No	Yes	See Table 3
No	N/A	N/A	No	No	N/A

Table 3. Software Workarounds for Problem 2

Master Mode	Cascade Mode	INT0 Priority vs. any INT1	INTA0 Problem	INTA1 Problem	Workaround
Yes	INT0 and INT1	N/A	Yes	Yes	Use only one interrupt line in cascade mode or H/W workaround
Yes	INT0 only	Lower	Yes	No	Make INT0 highest priority
Yes	INT0 only	Higher	No	No	N/A
Yes	INT1 only	N/A	No	Yes	See Table 2
No	N/A	N/A	No	No	N/A

## Hardware Workaround

1. Pull data bus lines 0 to 7 to a known value (using pull-up resistors) to force a defined value on the bus when the errata occurs.

These resistors will pull the floated bus to 0FFH during the 186 interrupt acknowledge cycle. A type 255 interrupt will be read from the bus and executed. An interrupt service routine for a type 255 interrupt should be included in the software. This solution allows a graceful recovery from the errata condition. If the current design uses interrupt type 255, the resistors can be selectively connected to  $V_{CC}$  or Ground to define an unused interrupt type.

2. Program cascaded interrupt inputs on the 186 to be level sensitive; otherwise, the 186 does not recognize that the interrupt is still active.
3. Write a simple service routine for the interrupt type defined in step 1.

Now that the system has recovered from the errata, the original interrupts must be serviced. The higher priority interrupt will execute next. Finally the interrupt request from the external interrupt controller must be serviced.

4. Write a simple service routine for an 8259 interrupt 7 (only for cases with two external interrupt controllers).

In systems with two external interrupt controllers. When the errata occurs because of a higher priority internal interrupt, the wrong INTA# signal will become active. If an 8259 receives an acknowledge and no interrupt is present, it assumes a spurious interrupt occurred and issues an interrupt 7. The service routine for this interrupt must be included in the software.

5. Issue non-specific End of Interrupt commands in INT0 and INT1 service routines (only for cases with two external interrupt controllers).

The situation where the interaction between INT0 and INT1 causes the errata is a special case. This situation will occur as just described, the INTA# pulse will be issued to the wrong 8259. In this situation, the interrupt input to the wrong 8259 is active when the acknowledge occurs. The acknowledged 8259 will drive its interrupt type onto the bus, and the CPU will service that interrupt. The only difficulty is what happens internally to the 186. The incorrect Interrupt Request and Service Bits have been set. To recover from this, the interrupt service routine must issue a non-specific End of Interrupt command. At this point, the wrong interrupt has been serviced correctly and because the interrupt inputs are configured to be level sensitive, the initial interrupt is now serviced.

**STATUS:** Fixed on C-Stepping. Refer to Summary Table of Changes to determine the affected stepping(s).

**AFFECTED PRODUCTS:**

80C186 XL/80C188 XL

80C186 EA/80C188 EA

80C186 EB/80C188 EB

80L186 EA/80L188 EA

80L186 EB/89L188 EB

## **2. *NMI Entering Powerdown Mode on the 80C186/80C188E A/EB/EC***

**PROBLEM:** If an NMI can be received during execution of the HLT instruction when entering Powerdown mode, certain considerations must be made.

**IMPLICATION:** If an NMI occurs during execution of the HLT instruction when entering Powerdown mode, the processor may enter Powerdown or may not service the NMI. To avoid this, the NMI pulse width must be extended to allow recognition.

**WORKAROUND:** NMI Functionality - NMI is the highest priority interrupt. It cannot be masked by software. To be recognized, NMI must be active for a minimum of one CLKOUT period and meet required setup and hold times (for recognition at a specific clock edge). If these requirements are met, NMI servicing begins at the next valid instruction boundary.

Powerdown Mode Functionality - Powerdown mode on the 186 processors causes the clock input to the CPU and peripherals to be disabled. To enter Powerdown mode, two things must happen. First, the PWRDN bit in the PWRCON Register must be set. Second, the HLT instruction must be executed. During the HLT instruction, the clock signal to the CPU and integrated peripherals stop (at a logic low level) at the end of the T2 bus state. The CLKOUT signal stops (at a logic high level) at the end of the T3 bus state. To exit Powerdown, an NMI or processor reset must occur.

NMI During HLT Execution - If an NMI occurs before the HLT instruction executes, everything functions properly. The NMI is recognized at the instruction boundary preceding the HLT instruction, the NMI is serviced and the processor then enters powerdown mode.

The problem occurs when an NMI occurs during execution of the HLT instruction. NMI is only serviced at valid instruction boundaries. The HLT instruction, when entering Powerdown, does not really have a boundary, it extends until Powerdown is exited. If NMI

occurs between the beginning the T1 bus state and the end of the T2 state, but does not extend into T3, it will not be recognized, and the processor will enter Powerdown mode. The processor does not recognize the NMI request during the HLT instruction until the internal clock has stopped (at the end of T2).

For the NMI to be recognized during the execution of the HLT instruction, the pulse must extend into T3. At this point, the processor has entered Powerdown and synchronized the NMI pulse. The NMI will be processed, but the processor will never enter Powerdown. Essentially, because NMI is active, the processor exits Powerdown as soon as it enters.

In a typical system design using Powerdown mode, NMI can only occur after Powerdown is entered and the clock is stopped. The simplest solution to the problem is to not assert NMI unless the processor has entered Powerdown Mode.

If the system requires periodic NMI pulses, then the NMI pulse width must be long enough to ensure that it will extend into the T3 state of the HLT instruction. A NMI pulse width of three CLKOUT periods guarantees this.

The figures below show NMI occurring at different times during execution of the HLT instruction. Two cases are shown. Figure 7 shows cases where NMI is not recognized. Figure 8 shows cases where NMI is recognized. Both cases assume setup and hold time requirements are met for the NMI input.




Figure 7. NMI Ignored During HLT Entering Powerdown




Figure 8. NMI Recognized During HLT Entering Powerdown

**STATUS:** There are no plans to correct this errata. Refer to Summary Table of Changes to determine the affected stepping(s).

### 3. *RESIN# Hysteresis*

**PROBLEM:** The Hysteresis on the RESIN# input pin is less than 100 mV. The data sheet specifies a minimum of 300 mV.

**IMPLICATION:** Simple RC reset circuits may not have a fast enough rise time to reset the device, and the pin will be more sensitive to noise.

**WORKAROUND:** For an RC reset circuit, choose components for a shorter time constant to obtain a faster rise time. An RC time constant of 50  $\mu$ s worked well in our bench tests, but you must test RC circuits carefully for your system. A better solution is to drive the input with a logic gate or provide Hysteresis via an external Schmitt trigger.

**STATUS:** Fixed in B step. Refer to Summary Table of Changes to determine the affected stepping(s).

#### 4. *TEST/BUSY#, RD#/QSMD#, LCS#, and UCS# Vil Problem*

**PROBLEM:** During RESET, the voltage necessary to force these pins to a logic "0" level is less than 100 mV.

**IMPLICATION:** This makes it more difficult to enter Numerics Mode (TEST/BUSY#), more difficult to enter Queue Status Mode (RD#/QSMD#), more difficult to enter ONCE Mode (UCS# and LCS#), and more difficult to enter factory test modes. The problem is most likely to occur when driving the pins LOW through a logic gate while noise is present. High supply voltages also aggravate the condition.

**WORKAROUND:** Workarounds are unnecessary unless the user desires one of the special modes. For the TEST/BUSY# pin, no workaround exists because it would be connected to an 80C187. For RD/QSMD#, LCS#, and UCS#, tie the pins directly to ground rather than through a resistor. Keeping  $V_{CC}$  to a closer tolerance than the 10% called for in the specifications also helps.

**STATUS:** Fixed in B step. Refer to Summary Table of Changes to determine the affected stepping(s).

#### 5. *Excessive Leakage in ONCE Mode*

**PROBLEM:** During ONCE Mode, weak internal pullups on MCS0#/PEREQ, MCS1#/ERROR#, RD#/QSMD#, and TEST#/BUSY do not turn off.

**IMPLICATION:** This situation causes leakage current in excess of the 10  $\mu$ A specified. Simulation indicates that the current should not exceed 5 mA per pin.

**WORKAROUND:** There is no workaround for use in test systems.

**STATUS:** Fixed in B step. Refer to Summary Table of Changes to determine the affected stepping(s).

## **SPECIFICATION CHANGES**

None for this revision of this specification update.

## SPECIFICATION CLARIFICATIONS

None for this revision of this specification update.

## DOCUMENTATION CHANGES

### 1. **82C59A Interface Pin Incorrectly Listed**

**ITEM:** On page 3-27 of the *80C186EA/80C188EA Microprocessor User's Manual*, Figure 3-24 (titled "Typical 82C59A Interface") incorrectly identifies a signal: "GCS0#" should be changed to "PCS0".

**AFFECTED DOCUMENTS:** *80C186EA/80C188EA Microprocessor User's Manual*, order #270950-003

### 2. **Reset State for Interrupt Mask Register Incorrectly Listed**

**ITEM:** On Page 8-17 of the *80C186EA/80C188EA Microprocessor User's Manual*, Figure 8-8 (titled "Interrupt Mask Register") incorrectly lists several reset states. The reset state for INT3:0 should be Fh, DMA1:0 should be 3h, and TMR should be 1h.

**AFFECTED DOCUMENTS:** *80C186EA/80C188EA Microprocessor User's Manual*, order #270950-003

### 3. **Incorrect Flow Chart Labels**

**ITEM:** On page 9-5 of the *80C186EA/80C188EA Microprocessor User's Manual*, Figure 9-3 contains incorrect flow chart labels. The stem below Conditional statement "Counter = Compare 'A' ?" should be a "YES" and the stem to the right should be a "NO."

**AFFECTED DOCUMENTS:** *80C186EA/80C188EA Microprocessor User's Manual*, order #270950-003

### 4. **Incorrect AX Register Contents**

**ITEM:** On page 2-16 of the *80C186EA/80C188EA Microprocessor User's Manual*, the contents of the AX Register in Figure 2-10, "Stack Operation," should be 12 34, not 10 50. (See the top box on the third step of the example, top right hand side of figure.)

**AFFECTED DOCUMENTS:** *80C186EA/80C188EA Microprocessor User's Manual*, order #270950-003